To: McComb, Martin[McComb.Martin@epa.gov]

Cc: Petri, Elliott[Elliott.Petri@WestonSolutions.com]; Jan Christner

(Jan.Christner@WestonSolutions.com)[Jan.Christner@WestonSolutions.com]; Dhieux,

Joyel[Dhieux.Joyel@epa.gov] **From:** Way, Steven

Sent: Sat 9/5/2015 10:20:42 PM

Subject: FW: Daily Flow Rates/Site Activities 05AUG2015

05AUG15 update.docx

This is what I want to get posted to the appropriate GK mine OSCWebsite. What's your recommendation?

Steven Way

Federal On-Scene Coordinator

Emergency Response Unit

US EPA - Region 8

1595 Wynkoop Street

Denver, CO 80202

Office: 303-312-6723

From: Gold King [mailto:goldkingrelease@gmail.com]

Sent: Saturday, September 05, 2015 3:54 PM

To: Way, Steven; Myers, Craig; Wardell, Christopher; rantham.nancy@epa.gov; Peterson, Cynthia; Weigel, Greg; silvertonfire@juno.com; Elliott.petri@westonsolutions.com; Isaac

Aboulafia; M.francis@erllc.com; ryan.c.schmid@uscg.mil; Lambie, Erin G CIV;

Gary Barnum; McKinstry, William A LCDR;

faliske.raymond@epa.gov; Larry Rader; roberto.n.trevino@uscg.mil; Dhieux, Joyel;

m.smith@erllc.com

Subject: Daily Flow Rates/Site Activities 05AUG2015

ALCON,

Attached is a summary of activities and future actions at the Gold King Mine site.

V/R

BMC Stamoulis